

**SONY**

**Car Stereo  
Service Bulletin**

Sony Service Company · Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XTC-100

**No. 235**

**Subject:** Part Number Corrections: CNJ-801 and CN-901

**Date:** June 10, 1992


**Symptom:**  
(\*\*)

The Service Manual contains errors regarding CNJ-801 and CN-901

**Solution:**

Please make the following corrections to your Service Manual.

REF.	INCORRECT		CORRECT	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
73	CONNECTOR, 10P	1-580-806-11	CONNECTOR, FEMALE 10P (CN-901)	1-580-807-11
CNJ-801	CONNECTOR, FEMALE 10P	1-580-807-11	CONNECTOR, 10P	1-580-806-11



Reference: FPR N1228

PRINTED IN U.S.A.  
CSA-14592-4

Tuner/Tape Deck  
**CSA-14**