

SONY.

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XES-X1

No. 237

Subject: Part Number Addition: Unilink Cable, Optical Cable

Date: June 22, 1992

Symptom:
(**)

Part numbers for the Unilink Cable and Optical Cable are missing from the Service Manual.

Solution: Please add the following part information to your Service Manual:

DESCRIPTION	PART NUMBER
CABLE, UNILINK	1-590-519-31
CABLE, OPTICAL	1-690-204-21

CSA-14 Pre-Amp/Signal Processor