

**SONY.**

Car Stereo  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XES-C1

**No.** 238

**Subject:** Part Number Addition: Unilink Cable, RCA Pin Cord

**Date:** June 22, 1992

**Symptom:**  
(\*\*)

The part numbers for the Unilink Cable and the RCA Pin Cord are missing from the Service Manual.

**Solution:** Please add the following part information to your Service Manual:

DESCRIPTION	PART NUMBER
CABLE, UNILINK, 5.5M	1-590-519-21
CORD, PIN, RCA	1-590-874-11

CSA-14 CD Player