

**SONY.**

Car Stereo  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XES-T1

**No.** 239

**Subject:** Part Number Addition: Unilink Cable

**Date:** June 22, 1992

**Symptom:**  
(\*\*) The part number for the Unilink Cable is missing from the Service Manual.

**Solution:** Please add the following information to your Service Manual:

DESCRIPTION	PART NUMBER
CABLE, UNILINK	1-590-519-11

CSA-14 Tuner/Tape Deck