

SONY.

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XES-P1

No. 240

Subject: Part Number Additions: Unilink, Optical,
Remote In/Amp Remote Cables

Date: June 22, 1992

Symptom:
(**)

Part numbers for the Unilink, Optical, Remote In/Amp Remote Cables are missing from the Service Manual.

Solution: Please add the following part information to your Service Manual:

DESCRIPTION	PART NUMBER
CABLE, OPTICAL	1-690-204-11
CABLE, UNILINK, 5.5M	1-590-519-21
CABLE, UNILINK, 2M	1-590-519-11
CABLE W/CONNECTOR (REMOTE IN/AMP REMOTE)	1-590-409-11

CSA-14 Pre-Amp/Signal Processor