

SONY

Car Stereo Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-7070


No. 256

Subject: Schematic Correction: +5V and +9V Lines

Date: September 17, 1992

Symptom: (**)
The schematic contains errors with respect to the +5V and +9V lines.

Solution: Correct the schematic in your Service Manual as follows:



CSA-14 Tuner/Tape Deck