

SONY

Car Stereo
Service Bulletin

Sony Service Company · Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-U8000

No. 261

Subject: Part Number Correction: Keyswitches S-801 Through S-828

Date: September 23, 1992

Symptom:


(**)

The part number shown in the Service Manual for keyswitches S-801 through S828 (located on the Display Board) are incorrect.

Solution:

Please make the following corrections to your Service Manual:

REFERENCE	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
S-801THRU S-828	SWITCH, KEYBOARD	1-692-037-41	1-692-037-11



CSA-14 Tuner/Tape Deck