

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-5180

No. 278

Subject: Part Number Addition: 8-pin Speaker Harness


Date: April 19, 1993

Symptom:
(**)

This model uses 2 different speaker harnesses: one which has a white 6-pin plug and the other which has a black 8-pin plug. The service manual only shows the part number for the one with the white 6-pin plug.

Solution: Order the speaker harness according to the type used in the unit being repaired.

REF	DESCRIPTION	PART NUMBER
13	SPEAKER HARNESS, 6-PIN	1-690-722-11
13	SPEAKER HARNESS, 8-PIN	1-690-722-21



CSA-14 CD Player



PRINTED ON RECYCLED PAPER

Reference: FPR O1053
Autoflagged - NO

PRINTED IN U.S.A.
CSA-14493-2