

**SONY**

**Car Stereo  
Service Bulletin**

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XR-5500

**No. 282**

**Subject:** Description & Part Number Correction - Reference  
No. Q-623, Transistor, 2SA1150

**Date:** April 30, 1993

**Symptom:**  
(\*\*)



The description and part number listed on page 29 of the Service Manual for Ref. # Q-623, Transistor, 2SA1150, is incorrect.

**Solution:**

Please note the correct description and part number as shown below.

REF	DESCRIPTION		PART NUMBER	
	INCORRECT	CORRECT	INCORRECT	CORRECT
Q-623	TRANSISTOR, 2SA1150	TRANSISTOR, 2SB772-Q	8-729-205-02	8-729-177-22

**CSA-14 CD Player**



Reference: FPR-01041  
Autoflagged - NO

PRINTED ON RECYCLED PAPER  
PRINTED IN U.S.A.  
CSA-14493-0