

SONY.

Car Stereo
Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-3050

No. 301

Subject: Schematic Error, Q701 and Q706

Date: October 19, 1993

Symptom:

(**)

The schematic incorrectly shows Q701 as PNP type, while in fact it is NPN type.
Also, the schematic shows Q706 as NPN type, while in fact it is PNP type.

Solution:

Please correct your service manual as shown below.

