

SONY

Car Stereo

CSA-14

Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-6077

No. 307

Subject: Part Number And Description Correction: IC51

Date: December 31, 1993

Symptom:



(**)

The part number and description shown in the service manual and supplement #1 for IC51 are incorrect.

Solution:

Correct the service manual and supplement #1 as shown below.

REF	DESCRIPTION		PART NUMBER	
	INCORRECT	CORRECT	INCORRECT	CORRECT
IC51 (MANUAL)	IC, LC6543H-3785	IC, LA1137M	8-759-821-95	8-759-821-73
IC51 (SUPP.#1)	IC, LA1137NM-TP T1	IC, LA1137M	8-759-821-96	8-759-821-73



Reference: D. Ponder
Autoflagged - NO



PRINTED IN USA
CSA-141293-2