

SONY.

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-5060

No. 320

Subject: Part Number Missing - Reference No. FE601,
Tuner (TUX-001) (FM/AM)

Date: April 26, 1994

Symptom:

(**)

The part number for Ref # FE601, Tuner (TUX-001) (FM/AM) is not listed in the parts list.

Solution:

Please add the following part number to the Service Manual.

REF	DESCRIPTION	PART NUMBER
FE601	TUNER (TUX-001) (FM/AM)	A-3282-000-A

