

SONY.

Car Stereo
Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-900

No. 331

Subject: Eliminating Alternator Noise.

Date: August 5, 1994

Symptom:
(54)

Alternator noise is heard from the speakers, particularly in European-manufactured vehicles using floating ground systems.

Solution:

Improved the ground of the unit by adding a grounding strap between it and a good chassis ground point on the vehicle. If necessary, use the screw listed below to connect the ground strap to the vehicle's chassis.

REF	DESCRIPTION	PART NUMBER
-	CORD W/ TERMINAL	1-575-060-11
-	SCREW (M4 X 6)	7-682-904-01

