SONY.

Hi-Fi Products Service Bulletin

Sony Service Company · Technical Services A Division of Sony Corporation of America Sony Drive, Park Ridge, New Jersey 07656

Model:

RM-P700E

No. 50

Subject: Incorrect Part Number

Date: November 22, 1988

Symptom: (**)

The part numbers for the plate (plastic overlay) and the batter lid are incorrectly listed in the manual.

Solution:

Please add the correct part numbers to your manual as shown below:

		Part Number	
Designation	Description	Former	New
21	Plate (Overlay)	9-994-255-01	4-922-255-01
2 5	Battery Lid	9-994-048-01	4-922-048-01

Miscellaneous

KCP