

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company · Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TA-F555ESX

No. 51


Subject: Pilot Lamps PL601 and PL602 Break **Date:** January 2, 1989

Symptom:
(13)

Please replace the pilot lamps with LEDs.

Solution:

Description	Part Number
Lamp PCB Assembly	X-4885-934-1



CSA-13 Amplifier

Reference: T/N DS088-0047

PRINTED IN U.S.A.
CSA-131286-1