

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: FH-150R

No. 53

Subject: Incorrect Part Number

Date: January 2, 1989

Symptom:
(**)

The part number listed in the service manual for IC601 is incorrect.

Solution:

Please revise your service manual with the correct part as listed below:

Designation	Description	Part Number	
		Former	New
IC601	STR4152 II	8-759-941-52	8-749-941-52

Compact Systems

CSA-13

Reference: FPR 000664

PRINTED IN U.S.A.
CSA-131288-8