

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive Park Ridge, New Jersey 07656

Model: CDP-S207

No. 98

Subject: Incorrect Part Number For
Optical Block


Date: January 19, 1990

Symptom:
(**)

The part number listed in the service manual is for a KSS-150 type optical block.

Solution: Please correct your service manual with the part number listed below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
917	Optical Block KSS-211	8-848-062-01	8-848- 131 -11



Compact Disc
CSA 13

Reference:

PRINTED IN U.S.A.
CSA131289-2