

**SONY**

# Hi-Fi Products Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** STR-GX10ES

**No.102R2**


**Subject:** Tuner Bleedthrough Into  
Other Modes

**Date:** January 31, 1992

This bulletin supersedes Hi-Fi Products Service Bulletin No. 102R1

**Symptom:**  
(54) If customer complains of FM bleedthrough, please add the following muting circuit:

**Solution:**



Receiver  
CSA-13

Reference:

PRINTED IN U.S.A.  
CSA-13192-1