

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TA-E1000ESD

No. 115

Subject: Part Numbers Correction

Date: April 10, 1990

Symptom:
(**)

The part number listed for IC106 on page 39 of the service manual is incorrect.

Solution: Please correct your service manual with the part number listed below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
IC106	RC4558P	8-759-995-08	8-759-945-58

CSA-13 Pre-Amplifier