

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-190/390/590

No.134

Subject: IC102 Failing

Date: October 25, 1990

Symptom:
(12)

If the unit comes to the Service Center because of a defective IC102, please perform the following procedure.

Solution: If this symptom occurs, replace IC102, and keep the unit running (by playing a disc) for two hours.

If IC102 does not get excessively hot, then release the unit to the customer.

If IC102 gets excessively hot and fails within two hours, then replace IC102, and perform two hours aging as above.

Compact Disc
CSA-13