

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-AV920/AV1020

No. 142


Subject: Service Manual Correction - Q707

Date: November 14, 1990

Symptom:
(**)

In both the schematic and board layout portion of the service manual, the base and emitter of overload detector transistor Q707 is incorrectly illustrated.

Solution: The Base and Emitter of Q707 should be reversed. Please correct your service manual as indicated below:



Receiver
CSA-13