

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C35/C201/C205/C305

No. 146

Subject: Incorrect Part Number - M101


Date: November 19, 1990

Symptom:
(**)

The part number for Spindle Motor, M101, is incorrectly listed in the service manual.

Solution: Please correct your service manual with the part number listed below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
M101	Spindle Motor	1-491-752-33	X-4917-523-3



Compact Disc

CSA-13