

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-AV920/AV1020

No. 147


Subject: Service Manual Correction -
IC701 Pin Out

Date: November 19, 1990

Symptom:
(**)

IC701 is shown reversed in the schematic diagram in the service manual. Pins 1 to 15 are listed in the wrong sequence, and B+ and B- are on the wrong inputs when the IC is shown correctly installed.

Solution: Please make the following corrections on page 20 of your service manual, and in the schematic on page 17.



Reference: FPR L1605

PRINTED IN U.S.A.
CSA-131190-6

Receiver
CSA-13