

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TC-W31

No. 158

Subject: Incorrect Part Numbers - Lid Assembly and Motor Assembly


Date: January 7, 1991

Symptom:
(**)

The Lid (B) Assembly cassette and the Motor (B) Assembly have incorrect part numbers listed in the service manual.

Solution: Please correct your service with the part numbers listed below:

Ref. No.	Description	Incorrect	Correct
2	Lid (B) Assembly, Cassette	X-3340-304-1	X-3346-304-1
M901	Motor (B) Assembly	X-3335-212-1	X-3358-212-1



CSA-13 Tape Deck

Reference: KCP

PRINTED IN U.S.A.
CSA-131290-7