

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company · Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TC-WR808M

No. 162

Subject: Part Number Correction - Plate
(C-Left), Side


Date: January 24, 1991

Symptom:
(**)

The part number listed in the service manual for the plate (C-Left), side (page 16, Ref. No. 10) is incorrect.

Solution: Please update your service manual with the correct part number listed below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
10	Plate (C-Left), Side	4-346-341-01	<u>3</u> -346-341-01



Reference: FPR L2223

PRINTED IN U.S.A.
CSA-13191-2

CSA-13 HFP