

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: DTC-75ES/55ES

No. 166

Subject: Intermittent No Loading or No
Ejecting


Date: February 8, 1991

Symptom:
(62)

Cassette loads and/or ejects intermittently.

Solution: If this symptom occurs, please add two spring steel plates
as shown below:

Description	Part Number
Spring Assembly, Plate	X-3362-655-1



CSA-13 DAT

Reference: SB AU90043

PRINTED IN U.S.A.
CSA-13191-7