

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TC-RX420

No. 170

Subject: Incorrect Part Number - IC307

Date: February 28, 1991

Symptom:
(**)

The part number listed in the service manual for IC307 is incorrect. It stipulates a 9-pin in-line IC (P/N 8-759-981-95), when the board requires an 8-pin in-line.

Solution: Please correct your service manual with the information listed below:

| Ref No. | Description | | Part Number | |
|---------|-------------|---------|--------------|---------------------------|
| | Incorrect | Correct | Incorrect | Correct |
| IC307 | RC4558S | M5218AL | 8-759-981-95 | 8-759- 634 -50 |

Tape Deck

CSA-13