

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-370/570

No. 180

Subject: E-F Balance Adjustment

Date: March 29, 1991

Symptom:
(**)

The E-F Balance Adjustment on page 7 of the service manual indicates that the procedure should be done with TP (GND) tied to ground; this is incorrect

Solution: The correct procedure is that TP (ADJ) and TP (TES) should be tied to ground.

Compact Disc
CSA-13

Reference: FPR M0658

PRINTED IN U.S.A.
CSA-13391-8