

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-GX40ES/-GX50ES/-GX60ES

No. 184

Subject: Bias Adjustment Procedure
is Incorrect

Date: March 29, 1991

Symptom:
(**)

The Bias Adjustment, listed on page 7 of the service manual, indicates that the adjustment should be done while measuring across R710 (LF) and R760 (RT). This is incorrect.

Solution: Measurement should be taken across R713 (LF) and R763 (RT).

Receiver
CSA-13

Reference: FPR M0456

PRINTED IN U.S.A.
CSA-13491-2