

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C100

No. 187

Subject: M602 Motor PC Board


Date: April 19, 1991

Symptom:
(**)

A replacement motor (P/N X-4308-360-A type FF-130SH) will be sent out whenever the M2 motor (A-4608-360-A) is ordered.

Solution: It is necessary to order the M2 P.C. board at the same time. This is because the new motor type does not fit on the old board.

Ref. No.	Description	Part Number
M602	Type FF-280SA	X-4308-360-A
919	PC Board, M2	1-626-868-11



Reference: FPR M0349, Manual Correct-1

PRINTED IN U.S.A.
CSA-13491-5

Compact Disc
CSA-13