

**SONY**

Hi-Fi Products  
**Service Bulletin**

Sony Service Company - Technical Services  
 A Division of Sony Corporation of America  
 Sony Drive Park Ridge, New Jersey 07656

**Model:** TC-W190/W295/W300/W310/W390

**No. 194**

**Subject:** Incorrect Part Number and Description


**Date:** June 12, 1991

**Symptom:**  
 (\*\*)

Reference no. 155 of Service Manual Supplement No. 1 for TC-W190/300, reference 418 in the TC-W310 and reference 315 in the TC-W295/W390 Manual are all listed as "Shaft, Pulley" with the part number 3-390-203-01. This is incorrect. The part numbers are also incorrect.

**Solution:** The correct part number is 3-390-803-01 and the part's correct name is a "bushing D"

Reference Number	Description		Part Number	
	Incorrect	Correct	Incorrect	Correct
155 (TC-W190/300)				
418 (TC-W310)	Shaft Pulley	Bushing D	3-390-203-01	3-390-803-01
315 (TC-W295/390)				



Reference: FPR #M1144, M1204

PRINTED IN U.S.A.  
 CSA-13591-12

Tape Deck  
**CSA-13**