

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TC-WR510

No.198


Subject: Part Number Correction - RV-301
Recording Balance Control

Date: June 26, 1991

Symptom: The part number listed on page 18 of the service manual for
(**) RV-301, Recording Balance Control, is incorrect.

Solution: Please note the correct part number shown below.

Reference Number	Description	Part Number	
		Incorrect	Correct
RV-301	Recording Balance Control	1-238-835-11	1-238-682-11



CSA-13 Tape Deck