

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TC-FX320/11/150/420R/422R/510R

No. 199R2

Subject: Part Number Change: Capstan Motor

Date: November 8, 1991

This bulletin supersedes Hi-Fi Products Service Bulletin No.199R1


Symptom:
(**)

The exploded view of the mechanism shown in the Service Manual indicates that the capstan motor should include a pulley.

Solution:

The original capstan motor has been replaced by a new type without a pulley. The motor pulley should be ordered separately. Refer to the chart below for the correct part numbers.

MODEL	MODEL REF. NO.	DESCRIPTION	PART NUMBER	
			FORMER	NEW
TC-FX320	M402	MOTOR	1-541-239-00	1-541-745-11
TC-FX11	M501			
TC-FX150	M501			
TC-FX420R	M401	PULLEY	----	X-3319-617-1
TC-FX422R	M401			
TC-FX510R	M802			



Reference: TC-03991

PRINTED IN U.S.A.
CSA-131191-2

CSA-13 Tape Deck