

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey, 07656

Model: CDP-C900

No. 228

Subject: Part Numbers For Bushing And Clip Not Referenced
In Service Manual


Date: December 23, 1991

Symptom:
(**)

The part numbers for the bushing (not shown at all) and the retaining clip are not referenced in the exploded view of the mechanism on page 27 of the Service Manual.

Solution: The correct part numbers for the bushing and retaining clip are as follows:

DESCRIPTION	PART NUMBER
BUSHING	3-701-438-01
RETAINING CLIP	4-926-218-01



Compact Disc
CSA-13

Reference: FPR-M2788

PRINTED IN U.S.A.
CSA-131291-1