

**SONY**

Hi-Fi Products  
Service Bulletin

**Sony Service Company** - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** STR-AV1020

**No.** 229

**Subject:** Replacement Part For Tuner Board Has Different Connectors.

**Date:** December 23, 1991

**Symptom:**  
(\*\*)

The replacement part for the tuner board has flat ribbon-type connectors which do not match the male push-in connectors on the main board.

**Solution:** The part number for the tuner board is incorrect as listed in the Service Manual. The part number listed is for a model STR-AV1010. The correct part number for the tuner board is as follows:

REFERENCE NO.	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
909	MOUNTED PCB, TUNER	A-4303-169-A	A-4303-283-A

Receiver  
CSA-13