

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C201/C205/C215/C225/C27/C305/C315/
C322M/C35/C37/C400/C401/C500/C515/C700/
C705/C715/C75ES/C8ESD/C800/C85ES,
SEN-301CD/311CD/501

No. 244R1

Date: October 30, 1992


Subject: Part Change: Disc Table

THIS SERVICE BULLETIN SUPERSEDES SERVICE BULLETIN NO. 244

Symptom: (**)
Disc tables supplied by KCP for replacement will be of the 2-hole type instead of the 1-hole type on some models.

Solution: Order the disc table having the desired finish from the chart below. The 2-hole type disc table replaces the 1-hole, 1-slot type disc table.

DESCRIPTION	FINISH	PART NUMBER
DISC TABLE	SMOOTH	4-926-383-01
	MATTE	4-926-383-11



Reference: FPR-M2473

PRINTED IN U.S.A.
CSA-131092-2

CSA-13 CD Player