

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: D-202

No. 248

Subject: Errors In Recharging Detection Voltage Adjustment

Date: February 19, 1992

Symptom:
(**)

On page 7 of your Service Manual, the recharging voltage adjustment specifies voltages on pin 5 and 6 of IC801. This is incorrect.

Solution: Correct the Service Manual as follows:

- V1: Voltage between IC802 5 Pin and GND
- V2: Voltage between IC802 6 Pin and GND

CSA-13 Discman