

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656


Model: CDP-S107

No. 266

Subject: Translation Board Marked Incorrectly: CLV and Sled Motor Connections. **Date:** May 29, 1992

Symptom: (**)
The connecting points on the translation board where the wires for the CLV motor and sled are soldered, are incorrectly marked.

Solution: The translation board should be marked as shown below:



Reference: FPR N0788

PRINTED IN U.S.A.
CSA-13592-1