

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-D2070X

No. 269

Subject: Incorrect Part Number Listed For IC302

Date: June 10, 1992

Symptom:
(**)

The part number listed for IC302 in the Service Manual Parts List is incorrect.

Solution:

Order IC302 using the part number shown below:

REF	DESCRIPTION		PART NUMBER	
	INCORRECT	CORRECT	INCORRECT	CORRECT
IC302	TL082ACP	TL082CP	8-759-503-91	8-759-990-82

CSA-13 Receiver