

**SONY**

Hi-Fi Products  
**Service Bulletin**

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** CDP-491

**No. 298**


**Subject:** Display Board Change

**Date:** October 30, 1992

**Symptom:**  
(\*\*) The display board layout has been changed along with IC401 which has been changed to a DIP package type component.

**Solution:** Refer to layout drawing below when troubleshooting and to order IC401, refer to part number shown in chart:

REFERENCE	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
IC401	IC uPD75212ACW-A23	8-752-817-41	8-759-058-72



(Continued)

Reference: FPR N1744

PRINTED IN U.S.A.  
CSA-131092-3

CSA-13 CD Player

CDP-491  
DISPLAY BOARD

