

**SONY**

Hi-Fi Products  
Service Bulletin

**Sony Service Company** - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** RM-P321/STR-GX69ES/GX99ES/D2090

**No. 305**

**Subject:** Record Learn and CD + 10 Functions not operational on RM-P321 remote commander

**Date:** December 30, 1992

**Symptom:**

(22)

The Record Learn function and the CD + 10 function are not operational on the RM-P321 remote commander.

**Solution:**

The symptoms described above are a result of a bug in the microprocessor in the RM-P321 remote commander. A new RM-P321 remote commander is available which incorporates an updated microprocessor that supports the Record Learn and CD + 10 functions. The new RM-P321 remote commander is available as shown in the table below.

**Note:** *Upgraded RM-P321 remote commanders should be distributed only to customers having specific complaints regarding the Record Learn and/or the CD + 10 function(s).*

DESCRIPTION	PART NUMBER
RM-P321 REMOTE COMMANDER	T-9985-510-1

CSA-13 Miscellaneous

