

**SONY**

Hi-Fi Products  
Service Bulletin

**Sony Service Company** - Technical Services  
A Division of Sony Corporation of America  
Sony Drive - Park Ridge, New Jersey 07656

**Model:** HST-221

**No. 306**

**Subject:** Part Description Correction -  
Reference No. R914, 1.2K, 5%, 3W  
Reference No. R608, 470K, 5%, 2W

**Date:** December 30, 1992

**Symptom:**  
(\*\*)

The Parts Description for Ref #'s R914, 1.2K, 3W and R608, 470K, 2W, shown in the schematic on page 20 of the Service Manual differs from the Parts List Description on page 44 of the Service Manual.

**Solution:** The Parts Description shown in the Parts List on Page 44 of the Service Manual is correct. Please note the correct part numbers as shown below.

REF	DESCRIPTION		PART NUMBER
	INCORRECT	CORRECT	
R914	1.2K, 3W	470, 5%, 2W	1-215-890-11
R608	470K, 2W	1.2K, 5%, 3W	1-216-481-11

CSA-13 Compact System

