

SONY.

Hi-Fi Products
Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics
Sony Drive, Park Ridge, New Jersey 07656

Model: CPM-300; D-122CK/802K; DCC-E55/E455/E905 **No. 352**

Subject: Cigarette Lighter Plug Blows Vehicle's Fuse **Date:** August 23, 1993

Symptom:
(11) The fuse in the vehicle's cigarette lighter circuit blows when the power cord plug is inserted into the lighter socket.

Solution: Replace the tip of the power cord plug with part shown below.

REF	DESCRIPTION	PART NUMBER
-	TIP, PLUG	4-962-384-01

