

**SONY** ..... Hi-Fi Products ..  
**Service Bulletin**

**CSA-13**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** D-113CR

**No. 364**

**Subject:** defective display (main board cracked)

**Date:** December 10, 1993


**Symptom:**

(13) Defective Display caused By A Crack In The Main Board Between IC801 And LCD801.

**Solution:**

Add a cushion to the board's area where the crack occurred to prevent it from breaking again.

REF	DESCRIPTION	PART NUMBER
-	CUSHION	3-533-310-11



ADD CUSHION  
IN THIS AREA

Reference: FPR-03187  
Autoflagged - YES



PRINTED IN USA  
CSA-131293-1