

SONY

Hi-Fi Products
Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: MDS-101

No. 370

Subject: Non-Sony Discs Jam During Loading, Or Load Slowly

Date: February 18, 1994

Symptom:
(65)

In some units, discs which are not made by Sony may occasionally jam during loading, or may load slowly.

Solution:

If a unit is exhibiting this problem, install the parts kit shown below. The kit consists of an improved SHUTTER LEVER and TORSION SPRING.

REF	DESCRIPTION	PART NUMBER
-	LEVER (SHUTTER L) KIT	X-4944-745-1

