

SONY.

Hi-Fi Products
Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: MHC-2750/3750, ST-H2750

No. 387

Subject: Incorrect Display On The ST-H2750


Date: March 18, 1994

Symptom:

(13) The display is incorrect on the tuner portion (ST-H2750) of this model.

Solution:

The symptom described above is caused by a poor connection on the System Control 1 connector between the DXA-H2750/H3750 component and the ST-H2750. Secure the connection between the ST-H2750 and the System Control 1 connection on the DXA-H2750/H3750.



Reference: FPR-P0497
Autoflagged - NO



PRINTED IN USA
CSA-13394-1