

SONY.

Hi-Fi Products
Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: TC-WR901ES

No. 391

Subject: No Operation With Remote Commander


Date: April 26, 1994

Symptom:

(25) The unit will not respond to IR Remote Commands.

Solution: Install missing jumper wire, JW11, onto the Main board as shown below.

[MAIN BOARD]



Reference: Technical news AU-94001
Autoflagged - NO



PRINTED IN USA