

SONY.

Hi-Fi Products
Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: HCD-C70
HCD-C90

No. 392

Subject: No CD operation when connected to the PFJ-1
jig.

Date: May 13, 1994

Symptom:
(**)

CD operation is unstable or inoperable when connected to the PFJ-1 power supply.

Solution: Revise the wiring of the PFJ-1 as outlined below.

