

**SONY.**

Hi-Fi Products  
**Service Bulletin**

**CSA-13**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** DTC-59ES/690  
DTC-57ES/670/750

**No. 403**

**Subject:** Take-up Reel Cap Separates

**Date:** July 25, 1994

**Symptom:**  
(62)

A tape will not fully rewind, rewind may be noisy, stop while in play, or take-up reel won't turn.

**Solution:**

Replace the take-up reel with the improved part listed below.

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
365	TABLE ASSY (T) REEL	A-2003-710-B	TABLE ASSY (T) REEL	A-2003-710-D