

Hi-Fi Products Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: TC-WR80ES/WR820A/WR87ES/WR775/
WR590/WR535/WR545/WR635S/
WR670/WR690/WR701ES/WR720A/
WR720/WR801ES/WR790 **No. 410**

Subject: New Spring for Replacement Head Base Assembly **Date:** September 7, 1994

Symptom:
(**)

There are two types of head base assemblies and head base springs. Use the new type of head base spring (listed below) when the new type head base assembly is used

Solution:

FORMER		NEW	
DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
HEAD BASE SPRING	3-359-455-01	HEAD BASE SPRING	3-907-362-01




FORMER

FOR THE FORMER TYPE
ONE END OF THE HEAD
BASE SPRING IS HOOKED
ON TO THE SHADED
PORTION AS SHOWN



NEW

FOR THE NEW TYPE,
ONE END OF THE HEAD
BASE SPRING IS HOOKED
ON TO THE SHADED
PORTION AS SHOWN



TOP VIEW

HEAD BASE ASSEMBLY



Filename: HFP0410.SB
Directory: J:\SBDOC\SEP94
Template: C:\WINWORD\S_BULL.DOT
Title: New Head spring
Subject:
Author: Hoyt Wing Lee
Keywords:
Comments:
Creation Date: 09/07/94 2:06 PM
Revision Number: 2
Last Saved On: 09/07/94 2:06 PM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 1 Minute
Last Printed On: 04/01/96 10:54 AM
As of Last Complete Printing
Number of Pages: 2
Number of Words: 140 (approx.)
Number of Characters: 800 (approx.)